

## PRODUCT BULLETIN

Subject: LFP3000 Back Off Issues  
Date: 3-27-06  
Bulletin Number: 06-0328 LFP3000 Back Off Issues

---

Champion Laboratories/Luber-finer has received several complaints of LFP3000 lube filters backing off on Cummins applications. Upon investigation, we have found instances of the threaded stud on the engine being severely worn allowing this to occur.

Inspection of the threaded filter stud on these applications at time of service is recommended with immediate replacement if found worn or defective.

