

**Date:** July 15, 2016  
**To:** Luber-finer® Customers  
**From:** Luber-finer®  
**Subject:** Fuel Filter Height Difference

**Service Bulletin: 07-15-2016**

### Filter Height Difference — L7694F vs. OEM

There is a slight height difference between Luber-finer and the OEM filter, where Luber-finer's version is approximately 10mm shorter. The OEM filter has a foam wiper seal on the bottom of the filter that our filter does not have.

This section of foam does not serve a function because there is not excessive debris on the center tube in the housing. The top and bottom seals in our filter and the OEM filter are in the same location and both filters seal in the same manner.

### PART NUMBER: L7694F

<b>Part Description</b>	Cartridge Fuel Filter
<b>Outside Diameter</b>	3.71 [94mm]
<b>Inside Diameter</b>	.50 [13mm]
<b>Height</b>	6.86 [174mm]
<b>Packaged</b>	2 O'Rings
<b>Buyers Guide</b>	International 3004473C91; Fuel Water Coalescer Caterpillar 3762578; Caterpillar CT660 Truck used on Workstar Lonestar trucks with (w/CT13 eng.) Maxxforce 11&13 eng.

